S.O.T. Systems of Timor
+67077192122
Rua de Ai Meti Laran, Comoro, Dom Aleixo, Dili

PERFÍL SERVISU

Montadór andaime / rigger

Scaffolder / rigger

Konstrusaun no ofísiu edifísiu · ISCO-08 7119 / 7215

Montadór andaime harii no hasai andaime ne'ebé konstrutór sira servisu iha leten. Rigger prepara tali, kabu no ekipamentu hiit atu guindaste bele muda karga todan ho seguru. Estratéjia abilidade 2022 ida hein katak projetu konstrusaun iha Timor-Leste sei presiza rigger no montadór andaime balun, maibé menus liu traballadór konstrusaun.

APRENDE IHA TIMOR	**Seidauk iha kursu nasionál** Lista publikadu seidauk kompletu
DURASAUN KURSU	**Sei konfirma** Seidauk iha fonte publikadu
IHA TIMOR	**Nesesidade balun** Menus liu traballadór konstrusaun
RAI-LI'UR	**Seidauk iha programa ofisiál** Austrália: servisu saida deit ho oferta
SALÁRIU IHA TIMOR	**US$276 / fulan** Média ba traballadór ofísiu hotu iha Timor-Leste, la'ós servisu ida-ne'e mesak (Inkéritu Forsa Traballu 2021)

SAIDA MAK ITA HALO

Harii andaime: Lee planu no haree katak rai metin; Harii kanu, armasaun, ai-riin no eskada; Hasai andaime ho seguru bainhira servisu remata.

Prepara karga: Hili no kontrola tali, korrente, slinga no kait; Kesi karga atu nia balansu no la monu; Monta guindaste ki'ik, rolda no guinxu.

Orienta hiit: Fó sinál liman ka radiu ba operadór guindaste; Hadook ema bainhira karga la'o hela; Kesi hamutuk no hadi'a tali no kabu.

Servisu ho seguru: Uza sintu seguransa, kapasete no luvas iha fatin aas; Kontrola ekipamentu loroloron no hasai buat ne'ebé aat; Para servisu bainhira anin makas ka bainhira buat ruma la seguru.

Bazeia ba deskrisaun ILO nian ba grupu ISCO-08 7119, Traballadór estrutura edifísiu no ofísiu relasionadu seluk (inklui montadór andaime), no 7215, Rigger no traballadór kabu.

IHA NE'EBÉ ITA SERVISU

Fatin konstrusaun (Edifísiu aas, ponte no hadi'a); Portu (Servisu portu presiza abilidade ofísiu hanesan); Sentrál no rede eletrisidade (Halo sistema eletrisidade nasionál la'o mós); Mina no gás (Traballadór sira aprende rigging no andaime iha ne'ebá).

Ita servisu iha li'ur no aas husi rai, iha loron-manas, anin no udan. Servisu ne'e todan no sala ida bele kanek ita ka ema seluk, entaun ita tuir regra seguransa beibeik.

Estratéjia abilidade 2022 dehan katak traballadór husi indústria mina no gás aprende rigging no andaime iha ne'ebá, no abilidade ne'e bele uza iha indústria seluk. Nia hein katak projetu infraestrutura sei presiza liu traballadór konstrusaun

no operadór ekipamentu pezadu, no nesesidade ki'ik liu ba rigger, dogger no montadór andaime.

Iha 2017, traballadór estrutura edifísiu no ofísiu relasionadu, grupu boot ne'ebé montadór andaime parte ba, iha servisu lima ne'ebé kontrata ema foun barak liu.

SERVISU NE'E BA HAU?

Ita di'ak iha: Servisu iha fatin aas, Forsa isin, Tuir regra seguransa, Servisu hamutuk no sinál klaru, Hatene todan no balansu.

Ita gosta: Servisu iha li'ur, Projetu boot, Servisu ho liman, Tali, kesi no ekipamentu.

Servisu ne'e la ba ita se ita ta'uk fatin aas. Fatin servisu boot dala barak uza Inglés ba informasaun seguransa no sinál.

APRENDE IHA TIMOR-LESTE

- **Seidauk iha sertifikadu nasionál** · Lista títulu INDMO ne'ebé publika la iha kursu andaime ka rigging, no lista ne'e seidauk kompletu.

Fatin atu aprende, durasaun kursu no regra lisensa ruma ba servisu iha fatin aas ka ho guindaste: sei konfirma ho INDMO no SEFOPE. Diretóriu ne'e nunka hatudu kursu ka númeru ida se la iha fonte.

BA NE'EBÉ

- **Traballadór konstrusaun** · Servisu dahuluk; Certificate I–II in General Construction (ISCO 9313)
- **Montadór andaime ka rigger** · Aprende iha fatin servisu ho ekipa ho esperiénsia
- **Xefe andaime ka supervizór rigging** · Planeia servisu no kontrola ekipa depois esperiénsia tinan barak
- **Operadór ekipamentu pezadu** · Pasu seluk iha fatin servisu boot (ISCO 8342)

SERVISU IHA RAI-LI'UR HO SEGURU

- **Austrália: Pacific Engagement Visa** · Seidauk iha programa ofisiál ne'ebé haruka montadór andaime ka rigger Timor ba rai-li'ur. Pacific Engagement Visa Austrália nian simu servisu saida deit, maibé ita presiza oferta servisu uluk.

Labele selu ba 'fixer'. Tama de'it liuhusi SEFOPE, eskritóriu governu Timor-Leste ba servisu iha rai-li'ur. Ema ida labele fa'an fatin ba ita, no servisu loloos iha rai-li'ur nunka husu osan rekrutamentu.

FONTE

1. ILO, ISCO-08 unit groups 7119 Building frame and related trades workers not elsewhere classified and 7215 Riggers and cable splicers https://www.ilo.org/public/english/bureau/stat/isco/isco08/
2. APTC, Timor-Leste Skills Strategy 2022: §3.1 labour market analysis (oil and gas skills, infrastructure demand) and Annex I (INDMO qualification titles) https://24045200.fs1.hubspotusercontent-na1.net/hubfs/24045200/Files/Timor-Leste%20Skills%20Strategy%202023.pdf
3. SEJT, Labour Market Outlook No. 7, Feb 2018 (Enterprise & Skills Survey 2017: top five occupations by new hires) https://www.laohamutuk.org/DVD/2018/LMOFeb2018en.pdf
4. Pacific Engagement Visa: any occupation, job offer needed (employer fact sheet 2025) https://pev.gov.au/sites/default/files/2025-02/PEV%20for%20Employers%20Fact%20Sheet_2025.pdf
5. Labour Force Survey 2021, Table 29: average monthly wage of employees by occupation group https://www.ilo.org/sites/default/files/wcmsp5/groups/public/%40asia/%40ro-bangkok/%40ilo-jakarta/documents/publication/wcms_863064.pdf

Husi diretóriu servisu Servisu. Númeru hotu iha fonte; "sei konfirma" katak seidauk iha. https://servisu.oftimor.com/jobs-directory/scaffolder-rigger/